


SEAT TRIM PARTS



BBS

BSFT = BACK SEAT FRONT "T"

BSFC = BACK SEAT FRONT CORNER L/R

BSS = BACK SEAT SIDE

BSHC = BACK SEAT HINGE COVER

BSR = BACK SEAT REAR


TBS = TOP BACK SEAT

BBS = BOTTOM BACK SEAT

ST = SIDE OF TOP A = A CORNER

B = CENTER CORNER

1/2 MOON = LARGE CURVES = L:2



SEAT TRIM PARTS COST:

BACK (REST) SEAT PARTS:

TOP TBS... \$104

SIDE OF TOP (ST L OR R)... \$45.50 Each

SEAT SIDE 1/2 MOON LARGE CURVE... \$63.70 Each

BOTTOM BBS... \$104

SEAT LITTLE CORNERS A = \$46.40 X 4

SEAT LITTLE CORNERS B = \$46.40 X 4

SEAT LATCH PARTS PER REQUEST

BSR

BOTTOM SEAT PARTS:

FRONT "T" BSFT... \$149.50

SEAT REAR BSR... \$104

FRONT CORNERS BSFC... \$71.50 Each

SIDE BSS = L OR R... \$52 Each

HINGE CORNERS BSHC L OR R... \$71.50 Each

SEAT LITTLE CORNERS B = \$46.40 X 4

PONTIAC SEAT/CARGO TRIM AVAILABLE

**** CALL FOR PRICE QUOTE ****

We are the original manufacturer of Classic Nomad Stainless Steel Trim.

Please call or email us for our list of custom fabricated stainless steel products made to your specifications.

Below is a Specification Sheet for the trim, please kindly wait for it to load. Thanks!

We also have available:

1955 - 1957 Nomad

cargo trim

1955 - 1957 Safari (Pontiac) cargo trim

1955 - 1957 2 & 4 door wagon cargo trim

QUALITY AUTO REPAIR

RANDALL BOYCE

1755 OAKS AVENUE

MARSHALLTOWN, IA 50158

www.qualityauto56.com